
FIG.1
RELATED ART



: RESET PERIOD & ADDRESS PERIOD : SUSTAIN PERIOD SF3 SF2 SF1 SF4 SF5 FIG.2 RELATED ART SF6 SF7 32 16 8 4 2 1 1 FRAME (16.67ms) 64 SF8 128

ON OPF OFF OFF OFF SE sub-fields SF10 ON ON OFF OFF OFF SF9 ON ON ON ON ON ON OOFF 32 ON ON OFF 32 32 SF6 32 SF5 16 Gray Level Number: 64 SW sub-fields SF4 ∞ SF3 SF2 SF1 sub-field Weighting / Value 1

ON OFF OFF OFF OFF

Total Gray Level Number: 64x7=448

Gray Level Number: 7

	32	SF12	NO	H	H H	Ŧ	!	!	Ή	出	`		\	
SE sub-fields													1	
	32	SF11	ō	6	P	OF	P	OF	PF-	OF		m		
	32	SF10	N O	N O	N O	OFF	OFF	OFF	OFF	OFF		mber : 8	•	
	32	SF9	NO	N O	NO	NO	OFF	OFF	OFF	OFF	\rangle	Gray Level Number : 8	1	1
	32	SF8	N O	NO	NO	NO O	NO	OFF	OFF	OFF		Gray Lo		
	32	SF7	NO	NO	NO	NO O	NO O	N O	OFF	OFF				
	38	SF6	NO	NO	NO O	NO	NO	NO	NO	OFF	J			
SW sub-fields	16	SF5												
	\ ∞	SF4			Grav Level Number: 32								-	
	4	SF3												
	2	SF2			eve l eve									
70	<u> </u>	SF1			Č	5								
sub-field	Weighting) 		-									_	

Total Gray Level Number :32x8=256

Total Gray Level Number :128x6=768

